

MATERIAL SAFETY DATA SHEET

Page: 1

PRODUCT NAME: Bagged Mortar Mixes HMIS CODES: H FR P

PRODUCT CODE: Mason 100B

======= SECTION I - MANUFACTURER IDENTIFICATION _____

MANUFACTURER'S NAME: PAKMIX INC.

ADDRESS 605 INDUSTRIAL WAY

DIXON, CA 95620

EMERGENCY PHONE (707) 693-2919 **DATE PRINTED:**

INFORMATION PHONE: (707) 693-2919 NAME OF PREPARER: Pakmix Inc

====== SECTION II - HAZARDOUS INGREDIENTS/SARA III INFORMATION =========

REPORTABLE COMPONENTS

CAS NUMBER

VAPOR PRESSURE

WEIGHT

nn Hg @ TEMP **PERCENT**

Tri Calcium Silicate

TLV, 5 mg/ cubic meter (respirable dust)

TLV 10 mg/ cubic meter (total dust)

***No toxic chemical(s) subject to the reporting requirements of section 313 of Title III and of 40 CFR 312 are present. *** This MSDS is prepared to comply with the OSHA Hazard Communication Standard. (29 CFR 1910.1200) Unlisted ingredients are not 'Hazardous per this OSHA Standard and are considered to be trade secrets of Pakmix Corporation. Identities of trade secret ingredients will be made available following the procedures specified in the standard.

======= SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS ========

BOILING RANGE: n/a SPECIFIC GRAVITY (H2O=1): 2.55 VAPOR DENSITY: n/a **EVAPORATION RATE**: n/a

COATING V.O.C.: 0.00 lb/gl MATERIAL V.O.C.: 0.00 lb/gl

SOLUBILITY IN WATER: Slight 0.1- 1.0 % APPEARANCE AND ODOR: Grey powder with

sand ,possibly rock-Odorless

FLASH POINT: n/a
FLAMMABLE LIMITS IN AIR BY VOLUME-

METHOD USED: n/a LOWER: n/a UPPER: n/a

EXTINGUISHING MEDIA= n/a

SPECIAL FIREFIGHTING PROCEDURES

n/a

UNUSUAL FIRE AND EXPLOSION HAZARDS

n/a

STABILITY: Product hardens in 6-8 hours and becomes stable.

CONDITIONS TO AVOID

None known

INCOMPATIBILITY (MATERIALS TO AVOID)

Acids, Fluorine, any additive except Water

HAZARDOUS DECOMPOSITION OR BYPRODUCTS

Carbon Dioxide when ailed with Acids

HAZARDOUS POLYMERIZATION= Will not occur.

======= SECTION VI HEALTH HAZARD DATA =======================

INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Causes irritation of mucous membrane and respiratory passages.

SKIN AND EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Corrosive to skin and eyes. Akali burns to skin and eyes may result if contacted.

SKIN ABSORPTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Systematically toxic concentrations will probably not be absorbed through the skin.

INGESTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Single dose oral toxicity is low. No hazards anticipated from ingestion due to industrial exposure.

HEALTH HAZARDS (ACUTE AND CHRONIC)

Acute exposure; Wet portland cement can dry the skin and cause alkali burns. Portland cement dust can irritate the skin and upper respiratory system.

Chronic exposure; Portland cement dust can cause inflammation of the lining of the interior of the nose and inflammation of of the cornea. Individuals who are allergic to chronium may develop an allergic dermatitis. (Portland cement may contain traces of chromium)

CARCINOGENICITY= NTP CARCINOGEN= No IARC MONOGRAPHS= No OSHA REGULATED= No None.

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE

Persons with lung disease should avoid inhalation.

EMERGENCY AND FIRST AID PROCEDURES

Wash eyes immediately with water. If irritation persists, seek medical attention. For gross inhalation, remove person immediately to fresh air, give artificial respiration as needed, seek medical attention as needed.

====== SECTION VII PRECAUTIONS FOR SAFE HANDLING AND USE ========

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Use dustless methods (vacuum) and place into container for disposal, or flush with water. Do not dry sweep and disperse particles into the air. Wear protective equipment specified below.

WASTE DISPOSAL METHOD

This product does not meet the definition of hazardous waste under the U.S. EPA Hazardous Waste Regulations 40 CFR 261. State or local hazardous waste regulations lay apply if they are different from the federal regulations. Dispose of according to Federal, State, and Local regulations.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Avoid breakage of bagged material or spills of bulk material. Keep Dry.

OTHER PRECAUTIONS

None

RESPIRATORY PROTECTION

Only HIOSH-approved or MSHA-approved equipment should be used.

VENTILATION

Use sufficient local exhaust to maintain TLV's and PEL's.

PROTECTIVE GLOVES

Protect hands with by using rubber or leather gloves.

EYE PROTECTION

Use protective shield (safety glasses) when exposed to dust particles.

OTHER PROTECTIVE CLOTHING OR EQUIPMENT

Wear appropriate protective clothing. Launder contaminated clothing after use.

WORK/HYGIENIC PRACTICES

Avoid creating and breathing dust.

The information contained herein is based on data considered accurate. However, no warranty is expressed or implied regarding the accuracy of these data or the results to be obtained from, the use thereof. Pakmix Inc. assumes no responsibility for personal injury or property damage to vendees, users or third parties caused by the material. Such vendees or users assume all risks associated with the use of the material. Customers-users of silica must comply with all applicable health and safety laws, regulations and orders.